

PVA Release Coating 2

Technical Data Sheet

PVA Release Coating 2

COMPOSITION

Hydroalcoholic solution of PVA

HOW TO USE

Release agents for epoxy and polyester resins

HOW TO USE

Before starting an experiment, the molds must be cleaned of any other release agents.

Sprayers	Airless or Airmix Spray System
Nozzle	0.5 – 0.8 mm
Throughput / minute	300 – 500 grams
Cleaning Procedures	in cold moulds, mechanical action by tools and compressed air or water

Chemical properties (typical values):

Appearance	Blue liquid
Density at 20°C	0.9 – 1.0 kg/l
Carriers	Hydroalcoholic solution
Flash point	<24°C

Durability:

24 months in the original packaging

Packing:

250ml – 1Liter – 5Liter – 10Liter